ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
8

Ward Name
Kodigehalli

Street ID
W0615, W0609, W0594, W0592, W0617, W0619, W0695, W

Street Name
NA, Vydhi Hospital Main Rd, 1st Main Rd, 2nd Crs, 5th Crs, 1st Crs

Significant Landmark
Maruthinagara and Tatanagara

Segment No.
8/C-W0615/S121225

Total Length (m)
698.86

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	157.14	77.578153	13.049252	77.577882	13.047857	Maruthinagara 8th A Cross	cross road
2	203.14	77.567873	13.051172	77.569686	13.050712	RMV clusters, CP layout 2nd cross	cross road
3	181.44	77.577239	13.049352	77.576947	13.047737	Maruthinagara 4th cross road	cross road
4	157.14	77.578153	13.049252	77.577882	13.047857	Maruthinagara 7th cross	cross road

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to roads, drains, footpaths and park in ward no. 08 (Package includes 11 works of Rs 1010 lakhs)

Sanctioned Estimated Amount (Rs.)
101000000

Sanctioned Year
2016-17

Year
2016 - 2017

Type of Work
Others

Other Work Type
Rcc drain and CC road

Tender
Tender

Work Details

Job No. / Work Code
008-17-000035

Work Order No.
BBMP/EE/BTP/WO/20/2017-18

Work Order Date
21/11/2017

Period of Extention

Defect Liability Period From
21/11/2017

Defect Liability Period To
21/11/2021

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Name of Contractor
Sri.Pramod M/s Karthik enterprises

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
15086384.00

Phone No.	E-Mail ID
9886213563	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		mohamad ali

Date of Inspection	Remarks
11/10/2018	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0615, W0609, W0594, W0592,

Designation	Approver Name	Date	Target Date	Remark
CE	R L parameshwaraiah	25/10/2018	09/11/2018	As proposed
SE	Vasu K M	25/10/2018	09/11/2018	Completed
EE	Mohandas H.T	23/10/2018	09/11/2018	verified
AEE	Ranganath	23/10/2018	09/11/2018	verify
AE	Liyaquath ali	23/10/2018	09/11/2018	mobile verification is done
AE	Liyaquath ali	10/10/2018	09/11/2018	forwarded

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0615, W0609, W0594, W0592,